## Exhibit D

# TERMINAL INSPECTION FORM

Terminal F13-46-25-VILLE VA Code	Date
Representing Landlord:	Representing Tenant:
(signature)	(signature)
(print name)	(print name)
(company)	(company)

#### Instructions:

1. Inspect each item noted below.

 Place proper code in "Condition" column.
 2-Uns
 Use "Remarks" column for additional N/A-Not applicable information concerning conditions coded "2".

Provide a clear photo of all conditions coded "2". Label photo.

5. Be sure both representatives sign the inspection report.

### Condition-Legend

1-Satisfactory Condition 2-Unsatisfactory Condition

Facilities Use Only Engineering

File Report TWX for Pix

2.

Close File

OFFICE	COND.	REMARKS
Walls		SOME EXTERIOR POLICE BENT
Windows	1	
Doors	1	FRUIT WILDOWS DEED PAINT
Stairs & Handrails	1	
Ceilings	1	
Lighting	1	
Exit Sign	1	
Floors	i	
Heating	1	
Air Conditioning	2	Executive constants
Restrooms/Plumbing Fixtures	ĺ	EXCESSIVE CONDENSATION ON A/H
Water Coolers	2	DOCK NOT LOSKITH

DOCK	COND.	REMARKS
Bumpers/Edge Channel	1	But Lie LT 1 y 2,5 30.0 5 5
Dock Levelers	1	RECENTLY REPAIRED
Columns	1	EFAILETS
Overhead Doors/Track	1	
Stairs & Handrails	1	
Ladders & Handrails	1	
Ceiling/Skylights	)	
Walls	J	
Scale	N/A	
Floor	1	JOINTS ? POTHERES ZEPARED
Pipe Door Guards	1	TOTAL SECTION OF
Lighting/Trailer Lighting	1	
Personnel Doors	1	
Dock Office	1	
Dock Restroom	1	
Forklift Ramp		

BUILDING EXTERIOR	COND.	REMARKS
Roof	1	
Handicap Ramp	1	
Fascia & Siding	1	BENT SIDINU AT RAMP
Canopy	1	THE PART OF THE PA
Gutters & Downspouts	1	MIGGILLE ONE DONAGROUT

YARD	COND.	REMARKS
Concrete Apron	(	
Concrete Dolly Strips	HA	
Parking Bumpers	NA	
Yard Condition	2	POTHOLES - YOU CONTRACTED TO FIX

YARD	COND.	REMARKS
		REMARKS

Shrubbery/Landscaping	t	PALLEDAD TIES TO FIX
Sidewalks	(	
Storm Sewers & Catch Basins	1	
Yard Lights	1	
Fence & Gates	2	MOCKED DOWN IN REAR
Employee Parking Lot	1	the second of th
Scale	NA	

GARAGE	COND.	REMARKS
Wall Interior & Exterior	2	SEE PHOTO'S AND NOTES *
Windows	j	AND MOTO IN
Doors	1	
Stairs & Handrails	Ala	
Overhead Doors	ı	
Lighting	(	
Approach Aprons	1	
Drains	1	
Gutters & Downspouts	i	
Roof	1	
Pipe Door Guards	NA	
Restrooms	Ил	
Office	NA	
Heating	AA	
Air Conditioning	MA	
Equipment	Na	

#### OTHER ITEMS:

\* GARAGE BY ROUGH SLATE. INSULATION FALLING. DOESN'T SEEN LIKE IT IS BEING USED. ALMOST LOOKS ABANDONED.

GOME TRASH / PALLETS NEED CLEANED UP BOT NOT BAD.

From:

Subject: FW: Fishersville facility

Date: August 7. 2012 1:36:45 PM CDT

To:

20 Attachments, 946 KB

Mary, this is the info and pictures I sent to Jeanette at Conway.

From:

Sent: Monday, August 06, 2012 9:35 AM

(@con-way.com)

**Subject:** Fishersville facility

Good morning Jeanette,

I hope all is well. Here are some pictures that I took while I was there. A few things I noted that need repair:

The wall sheet by the ramp has been damaged
The fence in the rear of the yard has been knocked down
The downspout at the rear of the building is missing
I am not sure what to say about the garage. It almost seems abandoned and is in bad shape. What are your thoughts on this?

All in all I thought the property was in good/serviceable condition. Please reply with any issues you may have had.

Thanks,



























